DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

69.28 File #:

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-015137 Address: 333 Burma Road **Date Inspected:** 27-Jun-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Li Yang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A Weld Procedures Followed: **Electrode to specification:** No Yes No N/A Yes N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS: Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component: OBG Segment**

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Dan Hernandez was present during the times noted above to observe the fit up, welding and related activities associated with the fabrication of the San Francisco Oakland Bay Self Anchored Suspension Bridge at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

OBG Trial Assembly Yard

Segment 9BE/9CE

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as OBE9B-008. The welder is identified as #222396 and was observed welding in the 1G (flat) position using approved Welding Procedure Specification WPS-B-T-2231T.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as OBE9B-009. The welder is identified as #062092 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as OBE9B-010. The welder is identified as #048659 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

WPS-B-P-2214-B-U2-FCM-1.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as EP163-001-013. The welder is identified as #054467 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

Segment 9AW/9BW

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SP905-001-043. The welder is identified as #045193 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2233-B-U2-F.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as SP768-001-037. The welder is identified as #045193 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2213-B-U2-FCM-1.

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as BP097-001-038. The welder is identified as #045280 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2233-B-U2-F.

Segment 8CE

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a fillet weld joint. The Weld joint is designated as RETRO-G-01-B3-045 to 048. The welder is identified as #220013 and was observed welding in the 2F (horizontal) position using approved Welding Procedure Specification WPS-B-T-2132.

Segment 8BE

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a fillet weld joint. The Weld joint is designated as RETRO-G-01-B3-045 to 050. The welder is identified as #220066 and was observed welding in the 2F (horizontal) position using approved Welding Procedure Specification WPS-B-T-2132.

For the above mentioned welding activities ZPMC Quality Control (QC) Inspectors are identified as Wang Li Yang, Zhu Zhang Hai and Zhou Peng. QA Inspector observed QC Inspectors verify welding parameters. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Segment 9BE/9CE

This QA Inspector observed the removal of fit up plates from the interior of the Deck Plate transverse CJP splice by flame cutting.

Segment 8CW

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

This QA Inspector observed ZPMC personnel performing Magnetic Particle Testing on the FL3 Web plate at locations of removed temporary fillet welds from two temporary stiffeners at panel point 69.

Segment 9AW/9BW

This QA Inspector observed back gouging of the root pass on the Deck Plate I-rib CJP splice, cross beam side.

Lift 7 West

This QA Inspector observed grit blasting in progress on the interior of the lift.

Lift 8 East

This QA Inspector observed grit blasting was being performed on the exterior of the lift but was stopped by ZPMC production personnel due to rain.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.





Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez, Dan	Quality Assurance Inspector
Reviewed By:	Peterson,Art	QA Reviewer